

LOG OF BORING: BH-03 CORE-QAQC

EASTING: -80.4921 m

NORTHING: 43.4516 m

VALIDATION STATUS: FAILED - 2 Errors / 2 Warnings

PROJECT: Validation QA and QC Examples

PROJECT NO.: Validation QA and QC Examples


COMPLETENESS: 100%

DATE: 2026-08-05

SURFACE ELEVATION: 326.4

CONFIDENCE: 63%

QA/QC STATE: In Progress - Review Required



Validation Summary: 2 errors, 2 warnings - deliberate rock-core QA/QC exceptions.

Water Observations: Water encountered at 6.8 m; stabilized water level 5.9 m.

Notes: Focused rock-core QA/QC example for validation demonstration and training.

Reviewed By: Pending

Approved By: Pending

LOG OF BORING: BH-03 CORE-QAQC

EASTING: -80.4921 m

NORTHING: 43.4516 m

VALIDATION STATUS: FAILED - 2 Errors / 2 Warnings

PROJECT: Validation QA and QC Examples

PROJECT NO.: Validation QA and QC Examples


COMPLETENESS: 100%

DATE: 2026-08-05

SURFACE ELEVATION: 326.4

CONFIDENCE: 63%

QA/QC STATE: In Progress - Review Required



Validation Summary: 2 errors, 2 warnings - deliberate rock-core QA/QC exceptions.

Water Observations: Water encountered at 6.8 m; stabilized water level 5.9 m.

Notes: Focused rock-core QA/QC example for validation demonstration and training.

Reviewed By: Pending

Approved By: Pending