



GAEA Technologies

221 Laurel St
Cambridge, ON N3H 3Y6
Canada
Phone: 613-900-1950 Email: sales@gaeatech.com

Borehole Validation Report

Project ID:	Environmental Examples
Project Name:	Environmental Examples
Borehole	RW-01 LNAPL Monitoring and Recovery Well
X Coordinate:	548260
Y Coordinate:	4804120
End Depth:	30.00
Date Drilled:	August 27, 2026
Validated By:	Admin
Validation Date:	August 27, 2026
WinLoG Version:	6.10
Validation Engine:	2.2.0

Overall Validation Status

Validation:	Warnings
Completeness:	89%
Quality:	Good
Confidence Score:	80%

Validation Summary

Warnings:	1
Errors:	0

Validation Warnings

Message:	PID or VOC inconsistent with odour or laboratory results
Data Type:	Environmental Cross-Check
Depth:	9.75
Actual Value:	VOC=0, Odour=Strong petroleum
Expected Value:	Consistent supporting observations and laboratory results
Explanation:	Conflicting field and laboratory evidence can indicate data-entry, linkage, sampling, or instrument-response issues.
Potential Cause:	Field screening, odour observations, sample condition, laboratory results, or depth linkage may be inconsistent.
Potential Resolution:	Check calibration, units, negative observation phrases, sample depths and laboratory links; correct verified errors or document the technical explanation.



GAEA Technologies

221 Laurel St
Cambridge, ON N3H 3Y6
Canada
Phone: 613-900-1950 Email: sales@gaeatech.com

Borehole Validation Report

This report summarizes automated validation checks performed by WinLoG Professional. It is not a formal QA/QC certificate and does not constitute approval of the borehole record.