



GAEA Technologies

221 Laurel St
Cambridge, ON N3H 3Y6
Canada
Phone: 613-900-1950 Email: sales@gaeatech.com

Borehole Validation Report

Project ID:	Mining Examples
Project Name:	Mining Examples
Borehole	FS-01 Fracture Spacing
X Coordinate:	512345.7
Y Coordinate:	4876543.2
End Depth:	50.00
Date Drilled:	August 17, 2026
Validated By:	Admin
Validation Date:	August 23, 2026
WinLoG Version:	6.10
Validation Engine:	2.2.0

Overall Validation Status

Validation:	Warnings
Completeness:	100%
Quality:	Good
Confidence Score:	84%

Validation Summary

Warnings:	1
Errors:	0

Validation Warnings

Message:	Bedrock encountered unusually shallow
Data Type:	Lithology
First Depth:	0.00
Second Depth:	8.00
Actual Value:	0
Expected Value:	≥ 0.5
Explanation:	The rule detects an uncommon or internally inconsistent combination that requires review rather than automatic correction.
Potential Cause:	One or more related values, classifications, interval boundaries, or observations may be incorrect, or the condition may be unusual but valid.



GAEA Technologies

221 Laurel St
Cambridge, ON N3H 3Y6
Canada
Phone: 613-900-1950 Email: sales@gaeatech.com

Borehole Validation Report

Potential Resolution: Compare the flagged values with the original logs and adjacent intervals. Correct confirmed errors; otherwise document the field or engineering basis for accepting the condition.

This report summarizes automated validation checks performed by WinLoG Professional. It is not a formal QA/QC certificate and does not constitute approval of the borehole record.