



GAEA Technologies

221 Laurel St
Cambridge, ON N3H 3Y6
Canada
Phone: 613-900-1950 Email: sales@gaeatech.com

Borehole Validation Report

Project ID:	Environmental Examples
Project Name:	Environmental Examples
Borehole	TP-01 Environmental Test Pit
X Coordinate:	548235.4
Y Coordinate:	4817642.8
End Depth:	12.00
Date Drilled:	August 25, 2026
Validated By:	Admin
Validation Date:	August 25, 2026
WinLoG Version:	6.10
Validation Engine:	2.2.0

Overall Validation Status

Validation:	Warnings
Completeness:	100%
Quality:	Good
Confidence Score:	84%

Validation Summary

Warnings:	1
Errors:	0

Validation Warnings

Message:	Elevated PID or VOC in impacted material
Data Type:	PID/VOC
Depth:	4.75
Actual Value:	146
Expected Value:	<= 75 ppm
Explanation:	Elevated screening values in visibly or otherwise impacted material warrant confirmation and documented review.
Potential Cause:	The reading may reflect impacted material, instrument response, calibration drift, moisture effects, or an inconsistent material description.
Potential Resolution:	Verify instrument calibration and units, review odour, staining and NAPL observations, and consider confirmatory laboratory analysis.



GAEA Technologies

221 Laurel St
Cambridge, ON N3H 3Y6
Canada
Phone: 613-900-1950 Email: sales@gaeatech.com

Borehole Validation Report

This report summarizes automated validation checks performed by WinLoG Professional. It is not a formal QA/QC certificate and does not constitute approval of the borehole record.